

FITTER LOG

STARTED. 13-11-89 - 28-12-89

**B.R. 205/1**



B. A. ROBERTS. J. JENKINS. MON. 13-11-89.

156425. BOTH COOLANT SYSTEMS FILLED & SUMP OIL LEVELS CHECKED & FILLED. ALSO TOILET PAN REPORTED BLOCKED & WONT FLUSH. TANK FILLED. PAN CLEANED & REPAIRS TO FLUSH VALVE.
- 51418 CALL OUT LLANDUDNO BOTH ENGS CUTTING OUT. BOTH ENDS FILLED. ENGS RUN UP & TESTED.
- 53529 CALL OUT LLANDUDNO DR REPORTED GEAR SNIP IN ALL GEARS ON NO2 ENG. EXAMINED FREE WHEEL DEFECTIVE. ENG & FIDRIVE ISOLATED.
- 47201 CALL OUT NEW YARD DR REPORTED NO2 CAB FULL OF SMOKE & LOSS OF POWER. EXAMINED FOUND CAB HEATER SWITCHES BURNT OUT. E.F. RELAY TRIPPED NO2 CAB HEATER FUSES REMOVED FOR SAFETY. EF RELAY RESET. LOCO RUN UP & TESTED. CREWE MAINT INFORMED.
- 51800 CALL OUT LLANDUDNO DR REPORTED NO6 FUSE BLOWN ON POWER CIRC. NEW FUSE FITTED & TESTED.
- 142054 CALL OUT LLANDUDNO DR REPORTED NO ENG STOP  
55750 LIGHT. EXAMINED NEW BULB FITTED.  
D. HILL. M. PRICE.
- 51927 }  
51935 } CALL TO LLANDUDNO. DR REPORTED LWS'S CUTTING OUT  
ALL RAD'S FILLED LWS'S RUN UP & TESTED.
150122. }  
52122. } CALL TO LLANDUDNO. DR REPORTED L.W. HURD LAMP  
NOT WORKING FOUND BULB BLOWN & WIRE BURNED.  
WIRE REMOVED NEW BULB FITTED & TESTED.
52062. CALL TO LLANDUDNO DR UNABLE TO START NO1 ENGINE.  
EXAM & FOUND STARTER MOTOR STUCK IN RETARDER.  
RELEASED ENGINE RUN UP & TESTED.
- 53977 CALL TO LLANDUDNO. GUARD REPORTED BUZZER  
IN VAN NOT WORKING BUZZER ADJUSTED.  
& TESTED.
- 31123 CALL TO YARD REPORTED E.F.R. TRIPPED LIGHT  
BRIGHT. COVER REMOVED FOR ACCESS TO RELAY.  
RESET & TESTED.

TUES. 14-11-89.

B. A. ROBERTS. J. JENKINS. 6A.

156412 BOTH COOLANT SYSTEMS & SUMP OIL LEVELS  
156470 CHECKED & FILLED. ALSO NEW HEAD LAMP BULB  
FITTED ON 57412.

150119 CALL OUT LLANDUDNO GUARD REPORTED NO TRAIN  
57119 LIGHTS. EXAMINED. ALL LIGHTING CLUB TRIPPED &  
RESET. LIGHTS REGAINED.

51418 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT  
51568 ALL ENGS FILLED. ENGS RUN UP & TESTED.

~~53977~~ CALL OUT LLANDUDNO DR REPORTED AIR & AXLE  
53977 LIGHT NOT WORKING. EXAMINED FOUND ELECTRICAL  
CABLE TO NO2 FIDR UNCOUPLED. CABLE RETIGHTENED  
& SECURED.

150217 CALL OUT LLANDUDNO GUARD REPORTED WASH  
50217 BASIN TAP WORKING CONTINUALLY. EXAM Suction  
VALVE STUCK RELEASE & TESTED

156468 CALL OUT LLANDUDNO ENG KEEPS CUTTING OUT  
57468 EXAMINED SUMP OIL LEVEL LOW. SUMP OIL  
FILLED & TESTED.

D. HILL M. PRICE.

53938. } CALL TO LLANDUDNO DR REPORTED NO1 ENGINE  
54484. } SHUT-DOWN UNABLE TO RESTART FOUND COOLANT  
SYSTEM LOW FILLED ENGINE RUN UP & TESTED ALSO  
R.H. TAIL LAMP T/CAR NOT WORKING NOW BULB  
FITTED & TESTED

150122 } CALL TO LLANDUDNO GUARD. NO INTERLOCK  
57122 } LIGHT WORKING TESTED FOUND BULB R.H. SIDE  
DISPLACED. REPLACED & TESTED.

51920. } CALL TO LLANDUDNO DR REPORTED W/WIPER ARM  
54276 } UNCOUPLED ARM. REPLACED RESET & TESTED.  
ALSO AIR & AXLE LIGHT NOT WORKING T/CAR. FOUND  
BULB BLOWN NOW BULB FITTED & TESTED.

51418. CALL TO STATION DR REPORTED HEATER NOT WORKING.  
WENT TO LLANDUDNO. GLOW PLUG REMOVED. FOUND  
BURNT. UNABLE TO REPAIR SET TO CHATTER.

B. A. ROBERTS. I. JENKINS. WED. 15-11-89.

156470 ALL COOLANT SYSTEMS & BUMP OIL LEVELS CHECKED  
156440 & FILLED.

150135 CALL OUT LLANDUDNO DR REPORTED BRAKES WONT  
52135 RELEASE EXAMINED D.S.D. SWITCH STICKING.  
RELEASED & TESTED. A.O.C INFORMED.

53930 CALL OUT LLANDUDNO DR REPORTED ALL ENGS  
52056 CUTTING OUT ALL RADS FILLED ENGS RUN UP  
& TESTED

51903 CALL OUT LLANDUDNO T/TONE HORN NOT WORKING  
BOTH HORNS ADJUSTED & TESTED.

156425 CALL OUT LLANDUDNO GUARD REPORTED. DOOR  
51425 CONTROL PANEL COVER LOOSE & WONT LOCK.  
HINGE SCREWS SECURED & COVER LOCKED.

150116 CALL OUT LLANDUDNO DR REPORTED A.W.S ISOLATED  
52116 UNABLE TO CANCEL HORN. REPAIRS TO RESET  
SWITCH. A.W.S DEISOLATED & SEALED.

D. HILL M. PRICE.

51568 } CALL TO LLANDUDNO. DR REPORTED VACUUM LEAK. SLOW  
51418 } CROATING. EXAM & FOUND HIGH SIDE FLEX PIPE ON  
BUSHOR BUSH WORKING WASHOR MISSING NOW WAS FOR  
FITTED & TESTED 51568.

51424. CALL TO LLANDUDNO. Guard Reported NO LIGHTS  
IN T/CAR. WORKING FROM THROUGH CONTROL IN  
VAN. FOUND NO 6 FUSE BLOWN T/CAR NOW  
FUSE FITTED & TESTED.

156412. } CALL TO LLANDUDNO. DR REPORTED ENGINES COOLANT  
52412 } SYSTEM LOW SYSTEM FILLED ENGINES RUN UP & TESTED.

150122. } CALL TO STATION. Guard Reported TOILET BLOCKED  
52122 } WENT TO LLANDUDNO. WATER TANK FILLED  
FLUSH TESTED. & PAN CLEARED.

THURS. 16-11-89

B. A. ROBERTS. I. JENKINS. 6A.

156440 ALL COOLANT SYSTEMS & SUMP OIL LEVELS  
156405 CHECKED & FILLED.

53431 CALL OUT LLANDUDNO DR REPORTED BAD AIR LEAK  
FROM E.P. VALVE BOX. FORWARDED E.P. VALVE STUCK  
VALVE STRIPPED & CLEANED REPAIRS & TESTED

53432 CALL OUT LLANDUDNO DR REPORTED ALL ENGS  
51569 CUTTING OUT ALL RAD'S FILLED & SUMP OIL  
LEVELS CHECKED ENGS RUN UP & TESTED

142046 CALL OUT LLANDUDNO BOTH GEARBOX & TRANSMISSION  
55637 FAULT LIGHTS BRIGHT. FAULT RESET  
& TESTED.

150120 CALL OUT LLANDUDNO DR REPORTED N/WIPER WORKING  
52120 CONTINUALLY. WILL NOT SHUT OFF. REPAIRS TO CONTROL  
VALVE KNOB. & TESTED.

47306 CALL OUT NEW YARD LOCO WONT START EXAMINED  
COOLANT LEVEL LOW. LOCO BROUGHT ON DEPT  
HEADER TANK FILLED ALSO SEVERAL HOSE PIPE  
CLIPS IN ENG ROOM SCREWED UP & TESTED.  
D. HILL. M. PRICES.

51947 } CALL TO LLANDUDNO DR REPORTED ENGS CUTTING  
53634 } OUT ALL RAD'S FILLED ENGS RUN UP & TESTED

54232. CALL TO LLANDUDNO DR REPORTED INC SWITCH  
DEFECTIVE IN OPN. NO KEY WANTED. UNABLE TO  
REPAIR DR INFORMED NEW SWITCH WANTED. R.H.A.

150123. } CALL TO STATION. Guard Reported NO LIGHTS IN COACH  
52123. } ALL LIGHTING C.C.B. TRIPPED THEN RESET. LIGHTS TESTED OK

52056. } CALL TO LLANDUDNO. DR REPORTED NO 2 ENGS 52056  
53930 } WILL NOT START COOLANT FILLED SUMP OIL CHECKED  
ENGINE RUN UP & TESTED. ALSO BUZZER IN CAB  
53930 NOT WORKING ADJUSTED & TESTED.

156470. } CALL TO LLANDUDNO. DR REPORTED R.H. MAJOR  
52470 } & TAIL LAMPS NOT WORKING NOW BULBS FITTED  
& TESTED.

B.A. ROBERTS - I. JENKINS 6A. FRI. 17-11-89.

156405 CALL COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED  
147032 - FINISHED.

53932 CALL OUT LLANDUDNO DR REPORTED NO 1 ENG WILL NOT  
START. EXAMINED RAD FAN BELTS MISSING ENG & FIDrive  
ISOLATED ALSO REPORTED BRAKES DRAGGING ON  
FRONT BOGIE. EXAMINED. BRAKES WORKING CORRECTLY  
A.O.C INFORMED.

156405 CALL OUT LLANDUDNO DR REPORTED MAIN GEAR BOX  
52405 TRANSMISSION FAULT LIGHTS BRIGHT. FAULT  
MEMORY RESET & TESTED OK.

53517 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT ALL  
53451 RAD'S FINISHED ENGS RUN UP & TESTED

51569 CALL OUT LLANDUDNO DR REPORTED SPEEDOMETER  
NOT WORKING. EXAMINED UNABLE TO REPAIR A.O.C  
INFORMED.

31312 CALL OUT NEWYARD LOCO FAILED ON FESTENING  
BRANCH. WHEELS SNAPPING. EXAMINED ALL SANDBOX  
M.T. NO SAND TO FILL SAME. LOCO TO WORK FORWARD  
CLEW MAINT INFORMED

D. HILL. M. PRICE.

47019 CALL TO YMR DR REPORTED BRAKE BLOCKS TO EXAM TTHN.  
EXAM LOCO TO WORK ONE TRIP ONLY. THN HAVE BLOCKS  
CHANGED ETC. - CROWD MAINT INFORMED.

156440. CALL TO LLANDUDNO DR REPORTED LMA STOP LIGHT  
BRIGHT. ALSO NO HSTAT. & LMA'S WILL NOT POWER UP. UNABLE  
TO REPAIR. SET TO HOME DEPOT. FOR REPAIRS. SUSPECT  
ALTERNATORS DEFECTIVE PLANT BATT'S. A.O.C. INFORMED

47358 CALL TO STATION DR REPORTED BAD AIR LOCK IN ENGINE  
ROOM FOUND BRAKE CUT-OUT VALVE STUCK NOT OPEN. VALVE  
REMOVED & TESTED.

53930 } CALL TO LLANDUDNO DR REPORTED LMA'S CUTTING OUT ALL  
52056 } RAD'S FILLED LMA'S RUN UP & TESTED.

150119 } CALL TO LLANDUDNO GUARD REPORTED CROW DOOR R.H.  
52119 } SIDS LOCK DEFECTIVE. LOCK REPAIRED & TESTED.

51973 CALL TO STATION DR REPORTED NO 1 LMA EXHAUST PIPES SEWY  
BLOWING FOUND BOLTS LOOSE ALL SCREWED UP & TESTED.

SAT. 18 - 11 - 89.

D. Hill. M. Price.

51907. } ALL COOLANT SYSTEMS & SUMP OIL LEVELS. CHECKED.  
156411 } & FILLED.

51907. ON EXAM FOUND EXHAUSTOR & ALTERNATOR BOLTS MISSING  
NO 2 ENGINE & ALTERNATOR BOLTS OFF PULLEY NO 1  
ENGINE NOW BOLTS FITTED & BOLTS REPLACED  
ADJUSTED. NO 1 ENGINE.

47371 CALL TO YARD DR REPORTED BAD COOLANT LEAK.  
PROS AND OF ENGINE FOUND HOSE PIPES LEAKING.  
CLIPS SCREWED UP & TESTED.

51509. } CALL TO LLANDUDNO. DR REPORTED ENG'S CUTTING OUT  
53224 } ALL RAD'S FILLED SUMP OIL LEVEL CHECKED.  
ENG'S RUN UP & TESTED

156426 } CALL TO STATION. DR REPORTED ENGINE COOLANT SYSTEM  
52426 } LOW SYSTEM FILLED ENGINE RUN UP & TESTED.

150124 } CALL TO STATION GUARD REPORTED COOLANT LEAK INSIDE  
57124 } COACH FROM ITATOR. SONT REMOVED FOUND HOSE  
PIPES LEAKING PIPES RESOT. CLIPS SCREWED UP SONT  
REPLACED & TESTED. REPAIRS CARRIED OUT @ LLANDUDNO.

53975. CALL TO LLANDUDNO DR REPORTED UNABLE TO START  
NO 1 ENGINE FOUND STARTER MOTOR STUCK IN 12V WHEEL.  
MOTOR REMOVED ENGINE RUN UP & TESTED. ALSO BOTH  
COOLANT SYSTEMS FILLED.

54266. CALL TO STATION. DR REPORTED BUZZER IN CAB NOT  
WORKING. SWITCH ADJUSTED & TESTED.

53198. } CALL TO LLANDUDNO. DR REPORTED ENG'S CUTTING OUT  
53244 } ALL RAD'S FILLED & SUMP OIL LEVEL CHECKED. ENG'S  
RUN UP & TESTED

142062. } CALL TO STATION. DR REPORTED GEAR BOX FAULT LIGHTS  
55712. } BRIGHT. RELAYS TRIPPED & RESOT. & TESTED.  
55758 }

SUN 19. 11. 89.  
D. Hill. M. PRICE.

150150 } ALL COOLANT SYSTEM'S & SUMP OIL LEVELS  
156411 } CHECKED & FILLED.

156411 Guard Reported TOILET PAN BLOCKED, & WILL NOT FLUSH.  
WATER TANK FILLED. FLUSH TESTED & PAN CLEARED.

47323 } BOTH LOCO. COOLANT SYSTEM'S FILLED FOUND LOW.  
47317 } ENGINES RUN UP & TESTED. FOR LEAKS NONE FOUND.

150150 } DR REPORTED W/WIPOR R.H. SIDE NOT WORKING KNOBS  
52150 } ON SPINDLE LOOSE REPAIRED & TESTED.

155311 } CALL TO STATION DR REPORTED R.H. HEAD LAMP NOT  
67311 } WORKING BULB BLOWN. NEW BULB FITTED & TESTED.

150265 } CALL TO STATION. GUARD REPORTED NO LIGHTS IN COACH  
52265 } ALL LIGHTING C.I.B'S TRIPPED THEN RESET. LIGHTS  
TESTED.

150119 } CALL TO STATION DR REPORTED LOCO. SHUT-DOWN.  
57119 } FOUND COOLANT LOW FILLED & TESTED.

156405 } CALL TO STATION GUARD REPORTED. HAND WASH  
57405 } BASIN BLOCKED. DRAIN PIPE REMOVED CLEARED.  
REPLACED & TESTED.

Mon. 20 - 11 - 89.  
D. Hill m. Pried.

156419. } ALL COOLANT SYSTEMS & Sump oil levels  
156470 } checked & filled.

R.B.R. 10254. CALL TO STATION. GUARD REPORTED KNOCKING  
UNDER COACH. LOADING BOGIE UNABLE TO FIND.  
FAULT. TRAIN FORWARD. A.O.C. INFORMED COACH  
TO HAVE FURTHER ATTENTION @ CREWS BY C+W.

156470. } CALL TO UNIT INSITU. DR REPORTED R.H. HAND LAMP  
52470 } NOT WORKING EXAM & FOUND BULB BLOWN & WIRE  
BURNED. WATER INSIDE LAMP. CLOURED WIRE REPAIRED.  
NEW BULB FITTED & TESTED.

51426. } CALL TO LLANDUDNO. DR REPORTED HAND CUTTING OUT ALL  
53171 } RAILS FILLED Sump oil levels checked ENG'S RUN UP & TESTED.

142012. } CALL TO LLANDUDNO. DR REPORTED COARBOX FAULT LIGHTS  
55603 } BRIGHT RELAYS TRIPPED & RESET & TESTED ON RETURN.

51947. CALL TO LLANDUDNO. DR REPORTED AIR & AXLE LIGHT NOT  
WORKING BULB CHANGED & TESTED. PANEL REMOVED FOUND  
WIRE TO LAMP HOLDER UNCOUPLED REPLACED & TESTED.  
PANEL REPLACED.

53634 CALL TO LLANDUDNO. DR REPORTED NO 2 ENG WILL NOT  
START COOLANT FILLED ENG RUN UP & TESTED.  
B.A. REBELLES. P. COX.

53930 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT. ALL RAILS  
52055 FILLED ENGS RUN UP & TESTED.

150137 CALL OUT LLANDUDNO DR REPORTED COUPLING PISTON STICK  
52137 OUT. PISTON RESET & TESTED.

53938 CALL OUT LLANDUDNO GUARD REPORTED BUZZER NOT  
WORKING IN BRAKE VAN. BUZZER UNIT ADJUSTED.  
& TESTED.

150150 CALL OUT LLANDUDNO GUARD REPORTED TOILET PAN  
52150 BLOCKED & WONT FLUSH. TOILET TANK FILLED & PAN  
CLEANED & FLUSHED.

156405 CALL OUT STATION ENG CUTTING OUT. EXAMINED COOLANT  
57405 LEVEL LOW. COOLANT FILLED ENG RUN UP & TESTED

Tues. 21. 11. 80.  
D. Hill M. Price.

156470 } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
156408 } CHECKED & FILLED.

156408 } GUARD REPORTED TOILET PAN BLOCKED & FLUSH  
52408 } NOT WORKING FLUSH TESTED & PAN CLEARED.

53932 } CALL TO LLANDUDNO. DR REPORTED ENGS CUTTING OUT.  
51569 } ALL RAD'S FILLED SUMP OIL LEVELS. CHECKED. NO2  
ENG SUMP FILLED 51569 ALL ENGS RUN UP & TESTED.

47323. A<sup>n</sup> EXM<sup>y</sup> CARRIED OUT. ALSO REPAIRS TO W/WIPER.  
DR'S SIDE NO1 ENG.

150124 } CALL TO LLANDUDNO. DR UNABLE TO RELEASE BRAKES  
52124 } AFTER UNCOUPLING. FOUND COUPLES RELAY STUCK RELEASED  
BRAKES RELEASED POWER RESTORED.

47306. CALL TO YARD DR REPORTED. TAIL LAMP NO2 ENG NOT  
WORKING NEW BULB FITTED & TESTED.

53253 } CALL TO LLANDUDNO. DR REPORTED ENG'S CUTTING OUT ALL  
51200 } RAD'S FILLED ENG'S RUN UP & TESTED.

B.A. ROBERTS. P. COX.

53576 CALL OUT LLANDUDNO DR REPORTED ALL ENGS CUTTING  
53442 OUT. ALL RAD'S FILLED. ENGS RUN UP & TESTED

150119 CALL OUT LLANDUDNO DR REPORTED BAD AIR LEAK BY  
57119 BATTERY BOX & FUEL TANK EXAMINED AIR - WATER SEP -  
ENTER VALVE LEAKING. VALVE RESET & TESTED OK.

53934 CALL OUT LLANDUDNO NO. TAIL LIGHTS IN TR  
54220 EXAMINED. LIGHTING RELAY STUCK RELEASED  
& TESTED OK.

150138 CALL OUT LLANDUDNO DR REPORTED AHS ISOLATED  
57138 HORN WILL NOT CANCEL OUT. DEISOLATED &  
TESTED NO FAULT FOUND. AHS SEALED.

156407 CALL OUT ~~STATION~~ STATION. S.S.M REPORTED E.B.S RAISED  
52407 @ PUNT BY DR. EXAMINED PASS COM PULLED IN  
TOILET. PASS COM RESET. E.B.S RESET. TESTED  
OK.

Wed. 22<sup>nd</sup> Nov 89.  
D. Hill. M. Price.

156419 } ALL COOLANT SYSTEMS + SUMP OIL LEVELS  
156408 } Checked + Filled.  
156424 }

53977 } CALL TO Llandudno Dr Reported engine cutting  
53529 } out ALL RAD'S filled Sump oil levels checked.  
engine Run up + tested.

53934. CALL TO Llandudno Guard Reported Heater not  
working Glow Plug removed cleaned Replaced + tested.

150231 } CALL TO Llandudno Dr Reported engine coolant  
52231 } Low engine cutting out. System filled also  
Sump oil topped up. engine Run up + tested.

31102. call to Yard Dr Reported Woodward Gov Low in  
Lub oil Filled + tested. Also fix Air Pips  
on Buffer Beam No2 and Washer missing now and  
fitted + tested.

156407 } CALL TO STATION Guard Reported Door "D"  
52407 } Locked out of use. Went to Llandudno, unable  
to Repair Door Locked. Booked 6 times, E.H.A.

150133 } CALL TO STATION. Guard Reported R.H. Crow Door  
52133 } Lock stuck in Released + tested.  
B. A. Roberts. P. Cox.

51947 CALL OUT Llandudno ENGS cutting out ALL RAD'S  
53634 Filled + Sump oil levels checked + filled

51901 CALL OUT Llandudno No Air + Axle Night Exam  
New Bulb fitted - tested

150123 CALL OUT Llandudno Toilet Pan Broken +  
52123 went Fresh. Toilet Tank N.T. Tank Filled  
Pan checked + flushed.

53932 CALL OUT Llandudno No2 Eng wont start Exam  
Starter Motor Pinion stuck in Flywheel  
Pinion released Eng Run up - tested.

THURS. 23<sup>RD</sup> NOV 89.  
D. HILL. M. PRICE,

156408. } ALL COOLANT SYSTEM & DUMP OIL LEVELS.  
156419 } CHECKED & FILLED.

53442. CALL TO STATION. DR REPORTED NO2 ENGINE NOT  
RUNNING. COOLANT FILLED. ENGINE RUN UP & TESTED.  
ALSO BRAKE VALVE STIFF TO WORK. VALVE OILED.  
& TESTED. REPAIRS CARRIED OUT @ LLANDUDNO

150132. } CALL TO STATION DR REPORTED CAB VERY COLD.  
57132 } HEATER WORKING OK. SET WORKED FORWARD

53198. } CALL TO LLANDUDNO DR REPORTED ENDS CUTTING OUT  
53244 } ALL RAS & FILLED. ENDS RUN UP & TESTED.

53516 CALL TO LLANDUDNO DR REPORTED. ONLY ONE TONE FRONT  
HORN ADJUSTED & TESTED.

6052 S.K. CALL TO STATION. GUARD REPORTED. POWER DOOR INSIDE  
COACH WILL NOT SHUT. AIR PRESSURE ADJUSTED - DOOR TESTED.

53977. } CALL TO LLANDUDNO. DR REPORTED NO AIR & AXLE LIGHT  
53529 } FOR 53529. EXAM BULB'S OK. BOTH ENDS. SUSPECT  
FAULT ON P/D. GLT SWITCH DR'S GOING OVER OK.  
SET WORKED FORWARD.

B.A. ROBERTS. P. COX.

53925 CALL OUT LLANDUDNO ALL ENDS CUTTING OUT. ALL  
52039 ENDS FILLED ENDS RUN UP & TESTED.

150129 CALL OUT LLANDUDNO DR REPORTED HEAD LAMP NOT  
57129 WORKING. EXAM NEW BULB FITTED & TESTED

156417 CALL OUT LLANDUDNO GUARD REPORTED L.H. FRONT  
52417 DOOR OPENS WHEN GUARD PASSES ACCESS CONTROL  
BUTTONS ARE PRESSED. EXAM EXTERIOR PASS OPEN  
BUTTON SWITCH STUCK IN. RELEASED & TESTED OK

150132 CALL OUT LLANDUDNO ENDS WEARS CUTTING OUT  
52132 EXAMINED DUMP OIL LEVEL LOW. DUMP OIL FILLED  
& TESTED OK.

FRI 24 - 11 - 89.  
D. Hill. M. PRICE.

156429. } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
156419. } CHECKED & FILLED.  
156408. }

47256 CALL TO YARD DR REPORTED W/WIPOR NOT WORKING  
NO LONGER REPAIRED & TESTED

53932. } CALL TO LLANDUDNO DR REPORTED W/VE'S CUTTING OUT ALL  
51569 } RAD FILLED W/VE'S RUN UP & TESTED

31120 CALL TO YARD DR REPORTED LOCO FAILED ON PESTINIOG  
BRANCH SKIPPING ALL SAND BOXES. M/T. NOW ON  
HAND LOCO WORKED FORWARD CROWS WANT INFORMATION

150119 } CALL TO STATION. DR REPORTED W/WIPOR NOT WORKING  
57119 } LOSS ON SPINDLE WENT TO LLANDUDNO ARM RESET & TESTED

150123 } CALL TO LLANDUDNO DR REPORTED A.W.S. WILL NOT  
52123 } ~~RESET~~ RESET. ISOLATED DISOLATED FOUND ROLLY  
STUCK REMOVED & TESTED

150225 } CALL TO STATION. DR REPORTED WATER HEATER  
82225. } IN CAB LOOKING. WENT TO LLANDUDNO FOUND  
HOSE PIPES RAKING PIPES REFITTED CLIPS SCREWED  
UP & TESTED

B.A. ROBERTS. P. COX.

51210 CALL OUT LLANDUDNO ALL ENDS CUTTING OUT ALL RADS  
53253 FILLED ENDS RUN UP & TESTED.

53982 CALL OUT LLANDUDNO HEATER NOT WORKING. EXAMINED  
NEW 25 AMP FUSE FITTED IN HEATER CONTROL PANEL

150150 CALL OUT LLANDUDNO GUARD REPORTED CROWN CAB  
57150 DOOR LOCK DEFECTIVE. LOCK & HANDLES REPAIRED

31120 CALL OUT NEW YARD LOCO WILL NOT START EXAMINED  
FOUND WOODWARD GOV TRIPPED RESET ROLL RUN UP  
& TESTED

B. A. ROBERTS. P. COX. SATURDAY. 25-11-89.

156419 ALL COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED +  
156401 FILLED. ALSO TOILET PAN BROKE ON 57419  
TOILET TANK FILLED. PAN CLEARED & FLUSHED.

51569 CALL OUT LHANDIDNO ALL ENGS CUTTING OUT. ALL ROPS  
53932 FILLED ENGS RUN UP & TESTED

156412 CALL OUT LHANDIDNO DR REPORTED ALL TRANSMISSION  
52412 FAULT LIGHT BRIGHT. FAULT RESET & RESET +  
TESTED OK.

156486 CALL OUT LHANDIDNO GUARD REPORTED NO TRAIN  
57486 HEAT. EXAMINED SALOON HEAT CCB TRIPPED RESET  
& TESTED OK.

142666 CALL OUT LHANDIDNO ENGS WONT START. EXHAF  
SHUT DOWN SOLENOIDS STICKING. RELEASED  
ENGS RUN UP & TESTED

53925 CALL OUT LHANDIDNO HEATER NOT WORKING. GLOW  
PLUG REMOVED - CLEANED, REPLACED & HEATER  
FIRED UP

SUN 26 - 11 - 89.  
BAROBURTS P. COX

156401 } ALL COOLANT SYSTEMS & SUMP OIL LEVELS  
150134 } CHECKED & FILLED.

156401 } GUARD REPORTED TOILET PAN BLOCKED & FLUSH  
52401 } NOT WORKING. WATER TANK FILLED. FLUSH TESTED.  
PAN CLEARED.

150134 } GUARD REPORTED R.H. CROW DOOR WINDOW STIFF  
52134 } PANEZ REMOVED FOR ACCESS TO "X" SPRING.  
FOUND BROKEN NEW SPRING FITTED PANEZ REPLACED  
& TESTED.  
ALSO SEVERAL SEAT HEAD REST DISPLACED. (10)  
SEAT REBUILT.

47241 CALL TO YARD. S.S.M. REPORTED LOCO IN  
COLLISION WITH 3 WAGONS. LOCO DAMAGED & 2  
WAGONS DERAILED. CROW BREAKDOWN. CALLED OUT.  
LOCO LIGHT TO CROWD MAINT INFORMED. (45 MPH.)

155305 CALL OUT STATION DR REPORTED R. TAIL LAMP NOT  
57305 WORKING. NEW BULB FITTED & TESTED.

156419 CALL OUT STATION DR REPORTED ENG CUTTING  
52419 OUT. RAD FIRED ENG RUN UP - TESTED.

47519 CALL OUT STATION DR REPORTED F.F. RELAY TRIPPED  
ALSO CAL - WATER FAULT RELAYS TRIPPED ALL  
RESET - TESTED OK.

B. A. ROBERTS. P. COX.

MONDAY. 27-11-89.

156486 AM COOLANT SYSTEMS - SUMP ALL LEVELS CHECKED +  
156419 FILLED.

47335 CALL TO LLOCH COOLANT SYSTEMS NOT. BOTH SYSTEMS  
47241 FILLED - SEVERAL HOSE PIPES SCREWED UP IN BOTH  
GROUP ROOMS.

150129 CALL OUT M. AND D. DR REPORTED ONLY ONE TONE ON  
52129 WARNING HORNS. EXAMINED PLASTIC CONNECTION CLIPPED  
ON TRUMPET. UNABLE TO REPAIR A.O.C. INFORMED.

51911  
54486 CALL OUT M. AND D. DR REPORTED HEATER NOT WORKING  
IN TICAL. EXAMINED UNABLE TO REPAIR A.O.C. INFORMED

51902 CALL OUT M. AND D. DR ALL ENDS CUTTING OUT ALL ROADS  
52049 FILLED ENDS RUN UP - TESTED.

31237 CALL OUT STATION DR REPORTED KOCO NOW IN POWER  
EXAMINED FOUND CONTROLLER UNLOCKED IN NO2 CAB  
CONTROLLER LOCKED KOCO TESTED OK.

150147 CALL OUT M. AND D. DR GUARD REPORTED NO DOOR  
INTERLOCK LIGHT. EXAMINED + BOTH SIDES DOOR  
CLOSE INTERLOCKS RESET + TESTED OK.

D. HILL. M. PRICE.

53294 } CALL TO LLOCH DR REPORTED ENG'S CUTTING OUT  
53216 } ALL RAD'S FILLED ENG'S RUN UP + TESTED. FOUND NO2  
ENGINE 53294. WILL NOT START. SYSTEM FUEL PUMP.  
DEFECTIVE KNOCKING BAD ENG + F/DR ISOLATED. TO CITATOR

150131 } CALL TO STATION GUARD REPORTED TOILET BLOCKED. WENT TO  
52131 } LLOCH DR WATER TANK FILLER FLUSH TESTED +  
PAN CLEAR.

156423 } CALL TO LLOCH DR REPORTED ENGINE LUB OIL  
57423 } LOW. SUMP FILLED ENGINE RUN UP + TESTED.

53512 } CALL TO LLOCH DR REPORTED ENG 2  
53934 } ENGINE 53934 WILL NOT START. FOUND STARTER  
MOTOR STUCK IN FLEWITZ. REMOVED ENGINE  
STARTED. ALSO ALL COOLANT SYSTEMS FILLED +  
TESTED.

B. ROBERTS. P. COX.

TUES. 28-10-89

156416 ALL COOLANT SYSTEMS - SUMP OIL LEVELS CHECKED  
156419 & FILLED.

156486 CALL OUT LLANDUDNO DR REPORTED ENG CUTTING  
OUT. EXAMINED SUMP OIL LEVEL LOW. SUMP OIL  
FILLED & TESTED.

156419 CALL OUT LLANDUDNO GUARD REPORTED A-1  
DOOR KEEPS OPENING. WITHOUT PASS ACCESS  
BUTTON BEING USED. EXAMINED OUTSIDE  
ACCESS BUTTON SWITCH STUCK IN. BUTTON  
RELEASED & TESTED OK.

53512 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT. ALL  
53934 LADS FILLED ENGS RUN UP - TESTED

51902 CALL OUT LLANDUDNO DR REPORTED NO.1 ENG LKA -  
HAUST JOINTS BLOWING. EXHAUST MANIFOLD NUTS  
SCREWED UP & TESTED.

52049 CALL OUT LLANDUDNO NO.6 FUSE BROWN ON  
POWER CIRC. NEW FUSE FITTED - TESTED, OK.  
D. HILL. M. PRICE.

53494 CALL TO LLANDUDNO DR REPORTED NO LIGHTS IN  
COACH. EXAM & FOUND FLAT BATTERIES. A.W.S.  
ISOLATED DR INFORMED DO NOT SHUT LNDG DOWN  
SOT WORKED FORWARD.

53925 CALL TO LLANDUDNO. DR REPORTED BAD AIR LEAK FROM  
E.P. VALVE BOX FOUND "FORWARD" E.P. VALVE STUCK REMOVED.  
STRIPPED CLEANED REPLACED & TESTED.

150147 } CALL TO LLANDUDNO. DR REPORTED R.H. HEAD LAMP  
52147 } NOT WORKING. FOUND BULB BLOWN. NEW BULB  
FITTED & TESTED

150118 } CALL TO LLANDUDNO GUARD REPORTED UNABLE  
52118 } TO OPEN TILLOT. DOOR. LOCK REMOVED REPAIRED  
REPLACED & TESTED

52039. CALL TO STATION DR REPORTED NO.2 ENGINES SHORT  
OF COOLANT ENGINES SHUT & OFF COOLANT FILLED  
ENGINES RUN UP & TESTED

B. A. ROBERTS. P. COX.

WED. 29-11-89.

156401 ALL COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED  
156406 & FILLED.

156401 CALL OUT LLANDUDNO AWS ISOLATED ENROUTE  
52401 UNABLE TO CANCEL. AWS DEISOLATED & TESTED  
UNABLE TO FAULT.

150133 CALL OUT LLANDUDNO TOILET PAN BLOCKED - WONT  
52133 FLUSH. REPAIRS TO FLUSH VALVE LINKAGE. PAN  
FIXED & CLEARED.

53512 CALL OUT LLANDUDNO NO 2 ENG WONT START. EXAM  
STARTER MOTOR PINION STUCK IN FLYWHEEL PINION  
RELEASED ENG RUN UP & TESTED.

51903 CALL OUT LLANDUDNO BOTH ENGS CUTTING OUT. BOTH  
RATS FIXED ENGS RUN UP & TESTED.

150204 CALL OUT LLANDUDNO SIGNAL BUZZER NOT WORKING.  
52204 REPAIRS TO BUZZER IDENTIFIED & TESTED.

D. HILL. M. PRICE.

53517 } CALL TO STATION DR REPORTED. AWS'S CUTTING  
53451 } OUT ALL RATS FILLED AWS'S RUN UP & TESTED.  
@ LLANDUDNO.

53438 CALL TO STATION. DR REPORTED NO 2 ENGINES WILL  
NOT START. EXAM & FOUND FUEL TANK M/T.  
ENGINE & F/DN ISOLATED.

51903. CALL TO LLANDUDNO. DR UNABLE TO START ENGS.  
EXAM & SUSPECT. FUSOR. BLOWN. UNABLE TO  
REPAIR. SET ISOLATED BOTH ENGS F/DN & D.S. D.

150229 } CALL TO LLANDUDNO DR REPORTED. UNABLE TO  
150204 } COUPLE SET. FROM 150204 UNABLE TO REPAIR  
BRAKE SETS UNCOUPLED & TESTED FROM 150229.  
NO FAULT FOUND.

53934 CALL TO LLANDUDNO. DR REPORTED. NO 1 ENGINES  
CUTTING OUT COOLANT SYSTEM FILLED ALSO  
SUMP OIL CHECKED & FILLED. ENGINES RUN UP  
& TESTED.

THURS. 30-11-89

B.A. ROBERTS. P. COX.

156401 ALL COOLANT SYSTEMS & SUMP OIL LEVELS  
156419 CHECKED - FILLED. ALSO TOILET PAN BLOCKED  
ON 52419. PAN CLEANED TANK FILLED &  
FLUSHED.

150135 CALL OUT RITCHIE UNIT FAILED. WILL NOT  
52135 MAINTAIN AIR PRESSURE ONLY ONE ENG  
RUNNING. ENG ON 52135 EXAMINED  
COOLANT LOW. COOLANT FILLED ENG  
RUN UP - TESTED OK. UNIT RIGHT TO  
BARNOR TO PICK UP WORKING.

52062 CALL OUT KHANDUDNO NO.1 ENG WILL NOT START  
EXAMINED FUEL SYSTEM AIR LOCKED. UNABLE  
TO REPAIR. UNIT LEFT IN SERVICE.

150117 CALL OUT KHANDUDNO DR REPORTED BSI  
57117 COUPLING PINION STUCK OUT. PISTON RESET  
& TESTED.

53451 CALL OUT KHANDUDNO NO.1 ENG WONT START.  
EXAMINED FUEL SYSTEM AIR LOCKED. UNABLE  
TO REPAIR UNIT FORWARD TO CHESTER.  
A.D.C. INFORMED

D. HILL M. PRICE.

53970. CALL TO LLANDUDNO DR REPORTED NO.2 ENGINES  
WILL NOT START. FUEL OIL & WATER CHECKED. FOUND  
STARTER MOTOR RELAY STUCK RELOADED ENGINES  
RUN UP & TESTED.

150225. } CALL TO LLANDUDNO GUARD REPORTED NO LIGHTS  
57225. } IN COACH ENGINES RUNNING ETC - ALL LIGHTING  
C.C.B.'S TRAPPED THAN RESET LIGHTS TESTED.

150116. } CALL TO LLANDUDNO GUARD REPORTED R.H.  
52116 } FAN TOR LOCK LIGHT NOT WORKING FOUND BULB  
DISPLACED. REPLACED & TESTED.

51920. CALL TO STATION. DR REPORTED CRB WATER  
MOTOR NOT WORKING WENT TO LLANDUDNO RESS  
RETURNED. & TESTED STILL NOT WORKING SET TO  
CHESTER.

B. A. ROBERTS. P. COX.

FRI. 1-12-89.

156419 ALL COOLANT SYSTEMS - SUMP and LEVELS  
156464 CHECKED - FILLED.

53534 CALL BUT LLANDUDNO ALL ENGS CUTTING OUT ALL RAD'S  
51505 FILLED ENGS RUN UP - TESTED.

156402 CALL OUT LLANDUDNO DR REPORTED R.H. TAIL LAMP  
57402 NOT WORKING. NEW BULB FITTED - TESTED.

57422 CALL OUT LLANDUDNO DR BRAKE VALVE STIFF TO  
OPERATE. VALVE CLEANED - TESTED OK.

150116 CALL OUT LLANDUDNO GUARD REPORTED TELEPHONE  
57116 DR TO GUARD NOT WORKING. EXAMINED MICRO SWITCH  
IN HANDSET LOOSE & STUCK IN. SWITCH SECURED  
& TESTED OK.

D. HILL. M. PRICE.

53294 } CALL TO LLANDUDNO DR REPORTED ENGS CUTTING  
53216 } OUT ALL RAD'S FILLED ENGS RUN UP & TESTED.  
FOUND NO 2 ENGINES & F/DR ISOLATED. 53216.  
NO LUB OIL IN SUMP. SET TO CILISTORE.

150140 } CALL TO LLANDUDNO DR REPORTED NO BUZZER IN  
52140 } CAB FOUND SWITCH STUCK FORWARDS & TESTED.

150117 CALL TO LLANDUDNO GUARD REPORTED TOILET BLOCKED,  
TANK FILLED. FLUSH TESTED & PAN CLEARED.

51950 CALL TO LLANDUDNO DR REPORTED NO 2 ENGINES  
WILL NOT START FOUND STARTER MOTOR STUCK IN  
FLYWHEEL REVERSE ENGINES RUN UP & TESTED.  
ALL COOLANT SYSTEMS FILLED.

SAT. 2. 12. 89.

D. HILL. M. PRICE.

156464 } CALL COOLANT SYSTEMS & SUMP OIL LEVELS  
150147 } CHECKED & FILLED.

53512. } CALL TO STATION DR REPORTED ENGR'S CUTTING OUT  
53934 } WENT TO LLANDUDNO ALL RAD'S FILLED SUMP OIL LEVELS  
CHECKED ENGR'S RUN UP & TESTED.

53534 } CALL TO BANBOR. A.O.C. REPORTED SET FAILED.  
51505. } EXAM & FOUND FLAT BATT'S. 53534 ENGR'S & P/D'S  
ISOLATED @ HOLYHEAD 51505 NO 1 ENGR'S. BAD FUEL  
LEAK ALSO LUB OIL LEAK. DIP STICK MISSING BOTH  
ENGR'S & P/D'S ALSO D.N.D. ISOLATED SET HAILED TO CHESTER.

47360 "A" EXAM CARRIED OUT.

47365. } BOTH COOLANT SYSTEMS FILLED & TESTED SEVERAL  
47227 } HOSE PIPE CLIPS. SCREWED UP.

53517. CALL TO LLANDUDNO DR REPORTED NO 2 ENGR'S  
EXHAUST PIPE BLOWING FOUND 3 BOLT JOINT ON  
MANIFOLD LOOSE ALL SCREWED UP & TESTED.

52049. CALL TO LLANDUDNO. GUARD REPORTED COACH DOOR L.H.  
SIDE LOCK DEFECTIVE. WILL NOT CLOSE. LOCK REMOVED.  
FOUND STUCK REMOVED. REPLACED & TESTED.

156407. CALL TO STATION. A.O.C. REPORTED ENGR'S WILL NOT  
START. ON EXAM FOUND ISOLATED BY FITTONE @  
CHESTER. SUSPECT FLAT BATTERIES. ALSO DR REPORTED  
UNABLE TO REPAIR BRACKETS @ PLINT. E.B.S. & T-15.  
ISOLATED SET M/T STOCK TO JCT. UNABLE TO REPAIR.  
TAKEN OUT OF SERVICE THEN BACK TO CHESTER T.M.D.

SUN. 3-12-89.

D. HILL. M. PRICE.

150120 AM COOLANT SYSTEMS + SUMP OIL LEVELS CHECKED +  
150213 FILLED.

150120 DR REPORTED ENG WONT START. EXAMINED FLAT BATT'S  
52120 UNIT PUT ON CHARGE. CIRC TESTED BATTERY CHARGE  
FUSE BLOWN NEW FUSE FITTED ENG RUN UP + TESTED  
ALSO (12) SEAT HEAD RESTS DISPLACED ALL SEATS  
REBUILT.

150213 GUARD REPORTED TOILET PAN BLOCKED + WONT FLUSH  
52213 TANK FILLED. PAN CLEARED. REPAIRS TO FLUSH  
VALVE LINKAGE. ALSO R.H. SIDE HEAD MARK BULB  
RENEWED - REPAIRS TO WIRES ON SAME.

156420 } CALL TO STATION. GUARD REPORTED R.H. INTERLOCK  
52420 } LIGHT NOT WORKING. FOUND BULB DISPLACED. REPLACED  
+ TESTED.

142057 } CALL TO STATION. DR REPORTED GEAR BOX TRAIL LIGHTS  
55540 } BRIGHT. RELAYS. TRIPPED THRU ROBOT. + TESTED.

150118 } CALL TO STATION. DR REPORTED ENGINES CUTTING OUT.  
57118 } COOLANT SYSTEM FILLED SUMP OIL LEVEL CHECKED.  
+ FILLED ENGINES RUN UP + TESTED.

MON. 4. 12. 89.  
D. HILL. M. PRICE.

156464 } ALL COOLANT SYSTEMS & SUMP OIL LEVELS  
156407 } CHECKED & FILLED.

156464 } DR REPORTED L.H. TRAIL LAMP NOT WORKING  
57464 } NOW BULB FITTED & TESTED.

47365 } BOTH COOLANT SYSTEMS FILLED ENGINES RUN UP  
47227 } & TESTED.

53216 CALL TO LLANDUDNO DR REPORTED BAD AIR LEAKS UNDER  
BUFFER BEAM. FOUND AIR PIPES NUTS LOOSE. SERVED  
UP & TESTED.

150231 } CALL TO LLANDUDNO DR REPORTED. ENGINES CUTTING OUT  
57231 } COOLANT FILLED ALSO SUMP OIL CHECKED & FILLED.  
ENGINES RUN UP & TESTED.

53645. } CALL TO STATION DR REPORTED ENGS CUTTING OUT ALL ROPS  
51496 } FILLED ENGS RUN UP & TESTED. REPAIRS CARRIED OUT  
@ LLANDUDNO.

53294. CALL TO LLANDUDNO DR REPORTED. AIR & AXLE LIGHT  
NOT WORKING NOW BULB FITTED & TESTED.

156401 } CALL TO LLANDUDNO. GUARD REPORTED PASS DOOR OPEN & I  
52401 } WHEN RELEASE BUTTON ARE ~~BEING~~ USED. EXAM & FOUND  
OUTSIDE PASS BUTTON STUCK IN RELEASED & DOORS TESTED.  
B. A. ROBERTS. P. COX.

53269. CALL OUT LLANDUDNO BOTH ENGS CUTTING OUT  
BOTH ENGS FUELLED ENGS RUN UP & TESTED OK.

156118. CALL OUT LLANDUDNO DR REPORTED CAB HEATER  
52118 BLOWING COLD AIR. HEATER BLED & TESTED OK.

51245 CALL OUT LLANDUDNO NO 1 ENG LIGHT NOT WORKING  
EXAMINED NEW BULB FITTED & TESTED.

156407 CALL OUT LLANDUDNO DR REPORTED GEARBOX  
52407 FAULT NIGHTS BRIGHT. TRANSMISSION FAULT  
LIGHTS RESET & TESTED OK.

THUR. 5-12-89.  
D. HILL. M. PRICES

156407 } ALL COOLANT SYSTEMS. & SUMP OIL LEVELS.  
156426 } CHECKED & FILLED.

53517 } CALL TO STATION DR REPORTED. NO 2 ENGINES CUTTING OUT  
53451 } 53517. ALSO R.H. HEATER NOT WORKING. 53451 WENT TO  
LLANDUDNO. FOUND SUMP OIL LOW. TOPPED UP. ALSO ALL RADS  
FILLED & BLOW PLUG. REMOVED CLEANED REPLACED & TESTED.

47213. CALL TO YARD DR REPORTED. BRAKE FLEX PIPE NO 2 END. HOLE.  
NEW PIPE FITTED & TESTED.

53529 CALL TO LLANDUDNO. DR UNABLE TO START ENGINES. COOLANT  
+ SUMP OIL CHECKED. ENGINES THEN RUN UP. FUEL SYSTEM AIR  
LOCKED. CLEARED. & TESTED.

47365. CALL TO YARD. DR REPORTED. UNABLE TO CREATE VACUUM. NO  
FAULT WITH ON AIR. FAULT FINDING. FOUND VACUUM  
RELAY VALVE STUCK. REVERSED & TESTED.

150122 } CALL TO LLANDUDNO. DR REPORTED. FOUND A.W.S. ISOLATED.  
52122 } DISOLATED & TESTED. UNABLE TO TRAVEL. TESTED ON  
RETURN TO JCT.

53975. CALL TO STATION. GUMED REPORTED. NO TRAIN LIGHTS FROM  
THROUGH CONTROL. WENT TO LLANDUDNO. FOUND NO 6 FUSE  
BLOWN. NEW FUSE FITTED & TESTED.  
B.A. ROBERTS. P. COX.

51462 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT ALL  
51511 RADS FILLED & SUMP OIL LEVELS CHECKED & FILLED

53977 CALL OUT LLANDUDNO DR REPORTED NO 6 FUSE BLOWN  
ON POWER CIRC. NEW FUSE FITTED & TESTED.

150143 CALL OUT LLANDUDNO ENG KEEPS CUTTING OUT  
57143 EXAMINED SUMP OIL LEVEL LOW. SUMP OIL FILLED  
ENG RUN UP - TESTED OK.

53216 CALL OUT LLANDUDNO DR SIDE WIPER ARM  
UNCOUPLED OFF SPINDLE. ARM REFITTED &  
ADJUSTED.

Wed. 6-12-89.  
D. Hill. M. Price.

156401 } ALL COOLANT SYSTEMS & SUMP OIL CHECKED  
156426 } & FILLED.

156401 } S.S.M. REPORTED TOILET PAN BLOCKED, WILL NOT  
52401 } FLUSH. WATER TANK FILLED FLUSH TESTED & PAN  
CLEARED.

53975. SOT IN SHED. COOLANT & SUMP OIL LEVELS CHECKED.  
FOUND NO.1 ENG FUEL SYSTEM AIRLOCKED BLED & TESTED  
FOUND REX EXHAUST PIPE BROKEN AND & R/Dz ISOLATED.

53294 } CALL TO LLANDUDNO DR REPORTED. ENGS CUTTING OUT  
53216 } ALL RAD'S FILLED SUMP OIL LEVELS CHECKED ENGS  
RUN UP & TESTED

47365. DR BROUGHT LOCO ON SITE LOW IN COOLANT SYSTEM  
FILLED. ENGS RUN UP. OUT OF COURSE.

150120 } CALL TO LLANDUDNO. GUARD REPORTED. R.H.  
57120 } INTERLOCK LIGHT NOT WORKING ~~ADJ~~ BY CROW.  
DOOR. FOUND BULB BROKEN. NOW BULB FITTED ETC.

53171 CALL TO LLANDUDNO. DR REPORTED. NO.2 ENG WILL NOT START  
FOUND STARTER MOTOR STUCK IN FLYWHEEL RELEASED & TESTED.

150143 } CALL TO LLANDUDNO. GUARD REPORTED. LOCK ON TOILET DOOR.  
52143 } UNCOUPLED. REPLACED & TESTED.  
B.A. ROBERTS. P. COX.

150129 CALL OUT LLANDUDNO H.C. KEERS TRIPPING & STOPPING  
57129 ENG. EXAMINED. UNABLE TO TAKE FAULT ENG ISOLATED  
H.O.C INFORMED.

51426 CALL OUT LLANDUDNO BOTH ENGS CUTTING OUT. BOTH  
RAD'S FILLED ENGS RUN UP - TESTED.

51906 CALL OUT LLANDUDNO BUZZER NOT WORKING. EXAMINED  
FUSE RENEWED IN BATTERY VAN - TESTED.

150130 CALL OUT LLANDUDNO UNIT WILL NOT COUPLE  
57130 UP. B.S.1 PISTON FOUND STUCK OUT. PISTON  
RESET, UNITS COUPLED & TESTED.

THURS. 7-12-89.  
D. HILL M. PRICE.

156426 } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
156401 } CHECKED & FILLED.

51426. CALL TO STATION. DR REPORTED NO2 ENG. SHUT-DOWN  
WILL NOT RESTART. COOLANT & SUMP OIL CHECKED ON ENGINES  
TESTED FOUND P/R SYSTEM AIR LOCKED UNABLE TO REPAIR  
@ LLANDUDNO. ENG & F/O R I ISOLATED.

53531 } CALL TO LLANDUDNO. DR REPORTED ENG. CUTTING OUT ALL  
53447 } RADY & SUMP OIL LEVELS. CHECKED & FILLED ENG. &  
RUN UP & TESTED.

47005. CALL TO YARD DR REPORTED WARTH FAULT LIGHT BRIGHT  
E.F.R. RESET. ENGINE RUN UP & TESTED.

53171 CALL TO LLANDUDNO. DR UNABLE TO START NO2 ENGINE  
COOLANT & SUMP OIL CHECKED ENGINE RUN UP & TESTED.

142053. } CALL TO STATION DR REPORTED ENG. CUTTING OUT LOW IN SUMP  
55703. } OIL ENGINE SUMP FOUND FULL. ENGINE RUN UP &  
TESTED SUSPECT OIL PRESSURE SWITCH DEFECTIVE 12.11.89.

150213. } CALL TO STATION GUARD REPORTED LIGHTS IN COACH NOT  
57213 } WORKING LIGHTING C.C.B'S TRIPPED THEN RESET LIGHTS TESTED.

150112 } CALL TO LLANDUDNO ENG. SHUT-DOWN. COOLANT FILLED.  
52112 } ENG. RUN UP & TESTED.

B.A. ROBERTS. P. COX.

53517 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT. ALL RADY  
53451 FILLED. ENGS RUN UP & TESTED OK.

51509 CALL OUT LLANDUDNO DR REPORTED NO1 ENG EXHAUST  
PIPE BLOWING. EXAMINED MANIFOLD JOINTS SCREWED  
UP & TESTED.

150143 CALL OUT LLANDUDNO DR REPORTED CHEN ACCESS  
57143 DOOR GUARDS SIDE WINDOW WILL NOT STAY SHUT  
EXAMINED X SPRING BROKEN UNABLE TO REPAIR  
WINDOW WEDGED WITH WOOD. A.O.C. INFORMED.

53216 CALL OUT LLANDUDNO PANEL LIGHTS NOT WORKING  
3 NEW BULBS FITTED & TESTED.

FRI 8.12.89.

D. HILL. M. PRICE.

156401 } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
156464 } CHECKED & FILLED.

51902. } CALL TO STATION DR REPORTED. ENG'S CUTTING OUT  
52049. } ALSO W/WIPER UNCOUPLED 52049. WENT TO LLANDUDNO  
ALL COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED &  
FILLED ALSO WIPER ARM REPLACED RESET & TESTED.

47365. "A" LEAKY CARRIED OUT. ALSO CAB DROP LIGHT WINDOW.  
2<sup>ND</sup> MAINS SIDE NOT END WILL NOT CLOSE. FOUND "X"  
SPRING. UNCOUPLED & STUCK. REPLACED & TESTED.

51950. CALL TO LLANDUDNO. DR REPORTED. HEATER NOT WORKING.  
GLOW PLUG REMOVED CLEANED REPLACED & TESTED.

150129. } CALL TO LLANDUDNO. GUARD REPORTED. HEATER IN CABIN  
52129. } UNDER SOFT LEAKING. SOFT REMOVED. FOUND HOSE PIPES.  
LEAKING. PIPES RESET CLIPS. SCREWED UP. & TESTED SOFT  
REPLACED.

150215. } CALL TO STATION. GUARD REPORTED. TOILET. DOOR LOCK  
57215. } DEFECTIVE. LOCK REMOVED. FOUND STUCK. RELEASED REPLACED W/O  
B. A. ROBERTS. P. COX.

53977 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT. ALL  
53529 RADS FILLED ENGS RUN UP & TESTED.

150123 CALL OUT LLANDUDNO A-WS EXHAUSTED EN-RAPPE  
52123 UNABLE TO CANCEL HORN. EXAMINED REPAIRS  
TO RESET BUTTON SWITCH & A-WS RESET  
- TESTED.

53981 CALL OUT LLANDUDNO HILL & HILL LIGHT NOT  
WORKING. EXAMINED NEW BULB FITTED & TESTED

156418 CALL OUT LLANDUDNO DR REPORTED GEAR  
57418 BOX TRANSMISSION FAULT LIGHTS BRIGHT  
FAULT REPAIRS RESET & TESTED OK.

B.A. ROBERTS. P. COX.

SAT. 9-12-89.

156464 ALL COOLANT SYSTEMS FILLED & SLUMP OIL LEVELS  
156419 CHECKED & FILLED.

53983 CALL OUT LLANDUDNO DR REPORTED HEATER NOT  
WORKING. EXAMINED GLOW PLUG DEFECTIVE. UNABLE  
TO REPAIR. A.D.C. INFORMED.

156418 CALL OUT LLANDUDNO DR REPORTED T.I.S SEAL MISSING  
52418 NEW SEAL FITTED.

51589 CALL OUT LLANDUDNO ALL ENDS CUTTING OUT ALL  
53224 RADS FILLED ENDS RUN LINE TESTED.

150126 CALL OUT LLANDUDNO DR REPORTED CAB HEATER  
57126 BLOWING COLD AIR. EXAMINED HEATER COOLANT  
SYSTEM BLED & TESTED OK.

53970 CALL OUT LLANDUDNO GUARD REPORTED UNABLE TO  
SWITCH TRAIN LIGHTS ON FROM B/VAN. EXAMINED  
NO.4 FUSE RENEWED & TESTED

47365 CALL OUT NEW YARD DR REPORTED SPEEDOMETER  
NOT WORKING BOTH ENDS. EXAMINED SPEEDO  
GENERATOR DEFECTIVE. LOCO NIGHT TO CREW.  
MAINT INFORMED.

B.A. ROBERTS. P. COX.

SUN. 10-12-84

150122 AM COOLANT SYSTEMS - SUPPLY LEVELS  
156419 CHECKED - FILLED.

47353 FAILED LATE SATURDAY. ENG WONT START  
EXAMINED PLAT BATTERIES. INT ON CHARGE ETC

150122 GUARD REPORTED TOILET PAN BLOCKED - WONT  
52122 FLUSH. PAN CLEARED - REPAIRS TO FLUSH  
VALVE. TANK FILLED

156419. TOILET REPORTED PAN BLOCKED - WONT FLUSH.  
PAN CLEARED - FLUSHED AFTER TANK FILLING  
ALSO L.H. HEAD BULBS RENEWED

150107 CALL OUT STATION GR REPORTED ENG WONT START  
57107 EXAMINED COOLANT NOW. COOLANT FILLED ENG  
RUN UP. TESTED

153306 CALL OUT STATION GUARD REPORTED BUZZER NOT  
52306 WORKING. BUZZER RELAY STICKING. RELEASED  
e TESTED OK.

B.A. ROBERTS. P. COX.

Mon 11-12-89

156418 ALL COOLANT SYSTEMS & SUMP ALL LEVELS CHECKED  
156426 & FILLED.

51902 CALL OUT LLANDUDNO ALL ENGS CUTTING OUT ALL RAD'S  
52049 FILLED ENGS RUN UP & TESTED.

47339 CALL OUT TO HOCO COOLANT LOW. COOLANT FILLED SEVERAL  
HOSE PIPE CLIPS SERVICED ENG RUN UP & TESTED.

156418 CALL OUT LLANDUDNO GUARD REPORTED L.H. SIDE DOOR  
WILL NOT OPEN OFF BUTTON ON 57418. EXAMINED  
UNABLE TO REPAIR. GUARD WORKED DOORS FROM 50418  
A.O.C INFORMED.

156401 CALL OUT LLANDUDNO ENG KEEPS CUTTING OUT EXAM  
57401 SUMP ALL LEVEL LOW, SUMP OIL FILLED ENG RUN  
UP & TESTED

150134 CALL OUT LLANDUDNO A.W.S ISOLATED ENVIRONS. A.W.S  
57134 DEISOLATED & TESTED NO FAULT FOUND A.W.S  
RESET.

51424 CALL OUT LLANDUDNO HEATER NOT WORKING. EXAMINED  
GLOW PLUG CLEANED. HEATER FIRED UP.  
D. HILL M. PRIES.

53451 } CALL TO LLANDUDNO DR REPORTED ENG'S CUTTING OUT  
53517 } ALL RAD'S & SUMP OIL LEVELS CHECKED & FILLED ENG'S RUN UP & TESTED.

150107 } CALL TO LLANDUDNO. DR REPORTED NO BUZZER EXAM  
52107 } & FOUND SWITCH STUCK RESET & TESTED.

53970 CALL TO LLANDUDNO. DR REPORTED NO 1 ENG WILL  
NOT START. EXAM & FOUND STARTER MOTOR RELAY  
STUCK RESET COOLANT SYSTEM FILLED SUMP OIL  
CHECKED ENG RUN UP & TESTED

150126 } CALL TO LLANDUDNO GUARD REPORTED R.H.  
57126 } INTER LOCK LIGHT NOT WORKING FOUND BULB  
DISPLACED REPLACED & TESTED.

53829. CALL TO STATION DR REPORTED NO 1 ENG SHORT  
OF COOLANT RAD FILLED ENG RUN UP & TESTED

B. A. ROBERTS. P. COX.

TUES. 12.12.89.

156426 AM COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED  
156464 - FILLED.

156419 CALL OUT STATION GUARD REPORTED FROM BRANCO  
155331 OUTSIDE HAZARD LIGHTS UP ON 155331. DOORS  
EXAMINED & CLOSED PROPERLY. TESTED OK.

51511 CALL OUT MANDUDNO AM ENGS CUTTING OUT  
51462 AM PADS FILLED ENGS RUN UP & TESTED

150140 CALL OUT MANDUDNO DR REPORTED B.S.1 COUPLER  
52140 PISTON STUCK OUT. PISTON RESET & TESTED

150130 CALL OUT MANDUDNO DR REPORTED W/WIPER  
52130 WONT WORK. REPAIRS TO CONTROL KNOB &  
TESTED OK.

51938 CALL OUT MANDUDNO DR REPORTED AM & AXLE  
LIGHT NOT WORKING IN FORWARD GEAR. REPAIRS  
TO PRESSURE SWITCH STICKING. TESTED OK

52065 CALL OUT MANDUDNO DR REPORTED <sup>NO ENG</sup> WILL NOT  
START. EXAMINED STARTER PINION STUCK OUT.  
PINION RESET ENG RUN UP & TESTED.

D. HILL. M. PRICE

51930. CALL TO LONDUDNO DR REPORTED NO 1 ENG SHUT-DOWN  
LOW IN SUMP OIL SUMP TOSTED. FOUND OK. COOLANT  
FILLED. ENG RUN UP & TESTED.

150134 } CALL TO STATION. DR REPORTED W/WIPER NOT  
52134 } WORKING FOUND CONTROL KNOB LOOSE ON SPINDLE  
REPAIR & TESTED.

51422. CALL TO LONDUDNO DR REPORTED NO 2 ENGINES  
CUTTING OUT RAD FILLED ENGINES TOSTED.

150120 } CALL TO LONDUDNO DR UNABLE TO COUPLE  
57120 } BOT. FOUND B.S.1 COUPLER PISTON STUCK OUT  
RESET & TESTED.

130108 } CALL TO STATION DR REPORTED W/WIPER NOT  
52108 } WORKING WIPER ARM LOOSE ON SPINDLE ARM  
ROBOT. SCREWED UP & TESTED REPAIRS CARRIED  
OUT @ LONDUDNO.

Wed, 13. 12. 89.  
S. Hill. P. Cox 06.00 M. Price 16.00.

156464 } ALL COOLANT SYSTEMS & PUMP OIL LEVELS.  
156405 } CHECKED & FILLED.

53934 } CALL TO Llundudno DR REPORTED ENGS CUTTING OUT  
53512 } ALL RAD'S FILLED ENGS RUN UP & TESTED.

53927 CALL TO STATION GUARD REPORTED HEATER NOT WORKING  
WENT TO LLUNDUDNO. NEW GLOW PLUG FITTED & TESTED.

150124 } CALL TO STATION. DR REPORTED W/WIPER NOT WORKING  
57124 } WENT TO LLUNDUDNO. FOUND WIPER ARM LOOSE ON SPINDLE  
ARM RESET. SCREWED UP & TESTED.

47283 CALL TO YARD DR REPORTED DROP LIGHT WINDOW 2ND  
MANS SIDE NO2 ENG. KEYS OPENING UNABLE TO  
REPAIR. WINDOW CLIPS MISSING I.H.D.

136418 CALL TO STATION GUARD REPORTED FAULT ON DOORS  
WENT TO LLUNDUDNO FOUND L.H. DOORS WILL NOT OPEN  
OFF BUTTONS. ON 57148. UNABLE TO REPAIR. TESTED  
FROM 52148 WORKED OK GUARD INFORMED. ALSO A.O.C.  
& S.S.M. SET TO CHASTOR.

53976 CALL TO LLUNDUDNO DR REPORTED NO2 ENGINE WILL  
NOT START. FOUND STARTER MOTOR STUCK IN 12V HOLD.  
RELEASED ENGINE RUN UP & TESTED.

51511 } CALL TO STATION. DR REPORTED ENGS CUTTING OUT  
51462 } ALL RAD'S FILLED ENGS RUN UP & TESTED @  
LLUNDUDNO

150108 } CALL TO STATION. GUARD REPORTED TOILET PAN  
52108 } BLOCKED WENT TO LLUNDUDNO. WATER TANK FILLED  
PUSH TESTED & PAN CLEARED. ALSO DR REPORTED  
ENG. WILL NOT RUN UP UNABLE TO REPAIR SET TO CHASTOR.

THURS. 14. 12. 89.  
D. Hill P. Cox 06.00 M. Price 16.00

156405. } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
156418 } CHECKED & FILLED

53934. CALL TO STATION. DR REPORTED W/WIPOR NOT WORKING.  
ARM LOCKS ON SPINDLE ARM ROBOT SCREWED UP & TESTED.  
REPAIRS CARRIED OUT @ LLANDUDNO.

51426 } CALL TO LLANDUDNO. DR REPORTED NO.2 ENGINE  
53171 } CUTTING OUT. <sup>51426</sup> ALSO TWO TONS HORN 53171 NOT  
WORKING. COOLANT SYSTEM FILLED. SUMP OIL LEVEL  
CHECKED. ENG. RUN UP & TESTED. HORN EXAM FOUND  
FULL OF SNOW. CLEARED OUT & TESTED.

156418 CALL TO LLANDUDNO. DR REPORTED FAULT ON DOORS  
EXAM & FOUND SAME FAULT. AS BOOKED ON 13112  
UNABLE TO REPAIR SET TO CHESTER A.O.C. INFORMED.

51903 CALL TO STATION. DR REPORTED W/WIPOR DEFECTIVE  
ARM ROBOT @ LLANDUDNO SNOW CLEARED FROM  
WINDSCREEN & TESTED.

142044 } CALL TO STATION. DR REPORTED GEAR BOX FAULT.  
55635. } LIGHTS BRIGHT. RELAYS RESET. WENT TO  
LLANDUDNO ON TEST RUN. FOUND OK.

150150 } CALL TO LLANDUDNO. GUARD REPORTED. R. IF TAIL  
57150 } LAMP NOT WORKING EXAM & FOUND FULL OF WATER  
& WIRES. BURNT REMADES. NOW BACK FITTED,  
& TESTED

51905. CALL TO STATION. DR REPORTED. NO.1 ENGINE  
CUTTING OUT. FOUND LOW IN SUMP OIL FILLED.  
ALSO. BOTH RAD'S FILLED. ENGS RUN UP & TESTED.  
REPAIRS CARRIED OUT @ LLANDUDNO

12. 89.  
D. Hill. P. Cox 06.00 M. Price 16.00.

156418 } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
156415. } CHECKED & FILLED.

53934. CALL TO STATION. DR REPORTED, W/WIPOR. NOT WORKING.  
WENT TO LLANDUDNO. WIPOR ARM LOOSE ON SPINDLE  
ARM REPT. & TESTED.

53531 } CALL TO LLANDUDNO. DR REPORTED, ENGS CUTTING  
53447 } OUT ALL RAD'S & SUMP OIL LEVELS CHECKED & FILLED  
ENGS RUN UP & TESTED.

150130. } CALL TO STATION. GUARD. REPORTED. TOILET FLUSH  
52130 } NOT WORKING. & PAN BLOCKED WENT TO LLANDUDNO.  
WATER TANK FILLED. FLUSH LINKAGE REPAIRED.  
& TESTED. PAN CLEARED.

51908. CALL TO STATION. GUARD REPORTED COACH DOOR LOCK  
DEFECTIVE. R.H. FRONT. WENT TO LLANDUDNO LOCK  
REMOVED. STRIPPED REPAIRED REPLACED & TESTED.

142009. } CALL TO STATION. DR REPORTED. ENGINES SHUT-DOWN  
55600. } WILL NOT RESTART. FOUND SUMP OIL LOW FILLED.  
ENGINES RUN UP & TESTED.

31324. DR BROUGHT <sup>LOCO</sup> ON SITE. LOW IN COOLANT. SYSTEM  
FILLED. ENGINES RUN UP & TESTED. RETURN TO  
SERVICE. OUT OF COURSE.

52056 } CALL TO LLANDUDNO. DR REPORTED. ENGINES  
53930 } CUTTING OUT. FOUND NO 2 ENGINE 52056. LOW  
IN SUMP OIL FILLED & TESTED. & NO 1 ENGINE  
53930. COOLANT FILLED & TESTED.

150124. } CALL TO LLANDUDNO DR REPORTED. L.H. MARKER &  
52124 } HEAD LAMPS NOT WORKING BULBS FOUND BLOWN.  
& WATER INSIDE LAMP. CLEARED NOW BULBS FITTED & TESTED.

53171 CALL TO LLANDUDNO DR REPORTED ENGINE PANEL LIGHT FOR  
NO 1 ENG. NOT WORKING. & AIR & AXLE LIGHT. NOW BULBS FITTED.

SAT. 16-12-89.  
D. HILL M. PRICE.

156415. } ALL COOLANT SYSTEM'S & SUMP OIL LEVELS.  
156405. } CHECKED & FILLED.

156415. } S.S.M. REPORTED SET IN SITU TOILET BLOCKED &  
52415. } FLUSH NOT WORKING. WATER TANK FILLED FLUSH  
TESTED NO FAULT FOUND PAN CLEARED.

51945. CALL TO STATION DR REPORTED NO.2 ENGINE NOT  
RUNNING. & W/WIPER DEFECTIVE. ENGINE RUN UP  
& TESTED. NO FAULT FOUND WIPER CONTROL KNOB  
LOOSE ON SPINDLE. REPAIRED & TESTED.

53512. CALL TO STATION DR REPORTED. R.H. CAB DOOR DROP  
LIGHT WINDOW WILL NOT ~~STAY~~ CLOSE. WENT TO  
LLANDUDNO PANEL REMOVED FOUND "X" SPRING  
UNCOUPLED. REPLACED & TESTED. PANEL REPLACED.

51902 } CALL TO STATION. DR REPORTED ENGINE CUTTING OUT  
52049 } WENT TO LLANDUDNO. ALL RAD'S & SUMP OIL LEVELS  
CHECKED & FILLED ENGINE RUN UP & TESTED.

142064 } CALL TO STATION DR REPORTED ENGINE SHUT-DOWN.  
55714 } WILL NOT RESTART. FOUND SUMP OIL LOW. FILLED.  
& BUILT. ENGINE RUN UP & TESTED.

53930. } CALL TO STATION DR REPORTED NO.2 ENG 53930 CUTTING  
52056 } OUT & W/WIPER ON 52056 NOT WORKING WENT TO  
LLANDUDNO. COOLANT SYSTEM FILLED ENG RUN UP & TESTED.  
W/WIPER ADJUSTED & TESTED.

150147 } CALL TO LLANDUDNO. DR REPORTED UNABLE TO COUPLE  
52147. } SET. FOUND COUPLER PISTON STUCK OUT RELEASED  
SET COUPLED. & TESTED.

51945. CALL TO LLANDUDNO. DR REPORTED NO AIR & AXLE LIGHT.  
ALSO BAD AIR LEAK EXAM & FOUND FLUX AIR PIPE TO  
NO.2 F/P. BURST. SET TAKEN OUT OF SERVICE &  
STOPPED NEW PIPE ORDERED FROM CRESTOR.

51245. } CALL TO LLANDUDNO DR REPORTED. ENGINE CUTTING OUT  
53269 } ~~ALL~~ ALL RAD'S & SUMP OIL LEVELS. CHECKED & FILLED  
ENGINE RUN UP & TESTED.

SUN. 17. 12 - 89  
D. HILL. M. PRICE.

156405. } ALL COOLANT SYSTEMS & SUMP OIL LEVELS.  
150121 } CHECKED & FILLED.

156405. } DR REPORTED W/WIPOR. CONTROL KNOB LOOSE ON SPINDLE.  
52405. } REPAIRED & TESTED ALSO TOILET PAN BLOCKED. WATER  
TANK FILLED FLUIT TESTED & PAN CLEARED.

150121 BURMA REPORTED SEVERAL SCATHING RUSTS DISPLACED.  
SUNTS REBUILT.

47365. }  
47354 } ALL COOLANT SYSTEMS FILLED & TESTED.  
31460 }  
31171 }

156425. } CALL TO STATION GUARD REPORTED R.H. INTERLOCK LIGHT  
57425 } NOT WORKING BULB DISPLACED REPLACED & TESTED.

150150 } CALL TO STATION. DR REPORTED W/WIPOR UNCOUPLED DR'S  
52150 } SIDE ARM REPLACED REOT & TESTED

156418 } CALL TO STATION. DR REPORTED L.H. INTERLOCK LAMP NOT  
52418 } WORKING NOW BULB FITTED & TESTED.

51418 CALL TO STATION. DR REPORTED NO 2 ENGINE SHORT  
OF WATER RAD FILLED & TESTED

MON 18.12.89

Air Thorp 1 Tentative

156464 } All coolant and sump oil levels  
156405 } checked and filled

53269 - Call to Wamawano - Reported door will not shut properly door done examined lock to renew door locked up and made safe.

51426 - Call to Wamawano - Reported N2 eng will not run examined found 15 lbs fuel starvation fuel system bled and eng tested OK.

51945 - Call to Station - pipe for 51945 coming on set from chest - pipe joined on 51945 eng. P.D. tested OK. all radii topped up

52060 - Call to Station - To ~~fit~~ fit head board. 15 set working the branch. head board fitted and secured.

51938 - Call to Wanduano - Reported N1 eng smoking examined oil dripping on exhaust pipe both rocker cover bolts tightened and sump topped up

180131 - Call to Wamawano - Reported eng will not run systems examined radii topped up and eng tested for leaks hose pipe clips on pumping pump tightened

142054 - Call to Wamawano - Reported eng racing. exam throttle cable linkage. both with jamming Throttle open linkage both recapped and eng tested OK

B.A. ROBERTS. P. COX.

MON. 18-12-89.

150116 CALL OUT LANDUTINO GUARD REPORTED NO TRAIN  
57116 HEATS. EXAMINED ALL LIGHTING CCB TRIPPED  
THEN RESET. LIGHTS REGAINED & TESTED.

150150 CALL OUT LANDUTINO DR REPORTED ENG CUTTING  
52150 OUT, EXAMINED SLUMP OIL LEVEL LOW. SLUMP OIL  
FILLED ENG RUN UP & TESTED

52065 CALL OUT LANDUTINO DR REPORTED CAB WINDOW  
WILL NOT SHUT PROPERLY. EXAMINED REPAIRS TO  
X SPRING.

150125 CALL OUT LANDUTINO TOILET PAN BLOCKED & WENT  
52125 FLUSH. EXAMINED TOILET TANK M.T. TANK FILLED  
PAN CLEARED & FLUSHED.

Tues 19.12.89.

Av. Thorp 1 Tenten's

156405 } All coolant levels and oil levels  
156464 } checked and topped up.

81462. - Call to Wandsworth - Reported eng will  
S1511. not start examined starter motor stuck in  
knocked out and tested OK. - S1511. Cab  
heater not working exam. motor will not run.  
Wiring exam looks ok. Suspect faulty motor

53171. - Call to Wandsworth - Reported eng  
cutting out examined eng over heating  
fault traced to fan belts slackened back  
fan motor adjusted tested OK.

150147 - Call to Wandsworth - Reported. very  
S7147 poor making air both air systems exam  
compressed air pipe fractured on S7147  
set worked forward. Chester control informed

53934 - Call to Station - Reported eng light bulbs  
missing bulbs replaced and tested OK.

81462 - Call to Wandsworth - Reported. rad cap  
missing (renewed) and. NED eng will not start  
exam. pinion stuck in could not rec fault. S/Time  
eng & drive isolated

47368 - Call to yard. - Requested brake block  
check to be carried out by crew maintenance  
control

150120 - Call to Station - Reported eng will  
S2120 not rev up systems examined but unable  
to find fault set worked forward Chester  
informed.

B.A. ROBERTS. P. COX.

TUES. 19-12-89.

147365. A. EXAMINATION CALLED OUT.

51905 CALL OUT LANDING BOTH ENDS CUTTING OUT BOTH  
RADDS FILLED. SUMP OIL LEVELS CHECKED ENGS RUN  
UP & TESTED.

142024 CALL OUT LANDING NO L.H. SIDE PASSENGER DOOR  
55565 VERY SLUGGISH IN CLOSING. EXAMINED FOUND LOCATION  
PIN ON BOTTOM OF DOOR SNAPPED OFF. PIN RESET  
& SECURED. DOOR TESTED OK.

150134 CALL OUT LANDING NO L.H. HEAD LAMP NOT WORKING  
57134 EXAMINED NEW BULB FITTED & REPAIRS TO  
WIRING.

Wed 20.12.89  
Alt Thorp 1. Jenkins

53516 }  
53442 } All rails and sumps checked  
156405 } and topped up  
186425 }

53516 - Call to Wandaano - Reported w/wiper  
not working wiper control valve adjusted  
and tested

156464 - Call to Wandaano - Reported eng  
52464 making high pitched noise examined  
rubbish caught in air intake removed  
eng tested now OK

150126 - Call to Wandaano - Reported w/screen  
87126 wiper arm uncoupled arm recoupled  
and reset to wiper on

52050 - Call to Scotti - Reported heater  
not working glow plug removed cleaned  
and fired heater. Tested OK.

51566 - Call to Wandaano - Reported w/wiper  
not working examined high tone temp  
adjusted and made to work.

B.A. ROBERTS. P. COX.

150118 CALL OUT WANDUANO DR REPORTED ENG CUT OUT WILL  
52118 NOT RESTART. EXAMINED COOLANT LEVEL NOW. COOLANT  
FILLED ENG RUN UP - TESTED.

150147 CALL OUT WANDUANO GUARD REPORTED INTERIOR CAB  
52147 DOOR LOCK ADRIPT & SCREWS LOOSE - MISSING.  
SCREWS REFITTED - LOCK SECURED.

51422 CALL OUT WANDUANO NO 1 ENG WONT START. EXAM  
STARTER MOTOR PINION STUCK OUT. PINION RESET  
ENG RUN UP - TESTED.

~~WANDUANO~~ CALL OUT WANDUANO DR REPORTED SELECTOR  
150415 SWITCH HANDLE ADRIPT. HANDLE REFITTED &  
SECURED.

Thurs 21-12-89.  
Arthrop 1 Jenkins

186425 }  
186464 }  
51421. }  
54275 }

All. rads and sumps checked.  
and Topped up

150138 - Call to Wandandno - Reported eng  
57138 will not run. all systems examined eng  
plug found to be loose. plug removed pins  
cleaned up. plug refitted eng tested OK.

~~150118~~ - Call to Wandandno - Reported bad air  
150118 leak examined drip cup blowing removed.  
57118 cleaned out and refilled air obtained.  
and cup tested OK.

53634 - Call to Wandandno - Reported bad air  
leaking fuel traced to throttle EP blowing  
worked manually a few times is clear  
tested OK.

31416 - Call to yard. - Reported cannot take  
power when changed over to vac fuel.  
Traced to change over switch faulty  
switch stripped and cleaned out with  
solvent switch refitted and tested OK.

51421. - Call to Wandandno - Reported bad  
blow on No 2 eng exam exhaust manifold  
3 bolts loose. bolts missing new bolts fitted  
BA Roberts. P. Cox.

57947. CALL OUT WANDANDNO DR REPORTED NO 2 ENG CUTTING  
OUT. EXAMINED. SUMP OIL LEVEL LOW. SUMP OIL TOPPED  
UP - TESTED OK.

51950 CALL OUT WANDANDNO BOTH ENGS CUTTING OUT. BOTH  
RADS FILLED. ENGS RUN UP - TESTED.

150120 CALL OUT WANDANDNO GUARD REPORTED TOILET PAN  
52120 BROCKED - NOT FLUSH. TANK FILLED. PAN CLEARED  
& FLUSHED.

FRI. 22-12-89.

Art. Duorp 1 Jenkins

156405 } all radios and sumps checked.  
156425 } and topped up.

31216 - Call 15 yard - Reported Woodward. Gov  
Sump low topped up and tested for leaks.

150116 - Call to Wanduano - Reported drivers  
57116 window will not stay shut examined  
window holding brackets screws missing  
new screws fitted tested OK.

51902 - Call to Wanduano - Reported. No1 eng  
will not run. Systems examined Radi. topped up  
and eng tested bad leak on cab water heater  
shut off cock. olive repositioned and nut  
tightened tested OK.

156444 - Call to Wanduano - Reported. horn will not  
work. examined horn operating handle. air  
fulcrum pin refitted and made secure.

150138 - Call to Station - Reported. water leak in  
coach. examined hose on water heater leaking  
clips slackened off and hose secured further on  
pipe

B.A. ROBERTS, P. COX.

156425 CALL OUT LANDIANO ENG WONT START EXAMINED  
52425 STARTER BATTERIES FLAT. ENG ISOLATED A.D.C  
INFORMED.

150119 CALL OUT LANDIANO W/NIPEL ARM LOOSE ON  
57119 SPINDLE. ARM SECURED - ADJUSTED & TESTED

51513 CALL OUT LANDIANO ENDS CUTTING OUT  
51800 ALL RADS FILLED ENDS RUN UP - TESTED.

51913 CALL OUT LANDIANO GUARD UNABLE TO SWITCH  
TRAIN LIGHTS ON FROM BRAKE VAN. EXAMINED  
NO4 FUSE BROWN FUSE RENEWED - TESTED

B.A. ROBERTS P. COX

SAT. 23-12-89.

150206 ALL RADDS & Sumps CHECKED - TOPPED UP.  
156461

53198 CALL OUT LLANDUDNO 7/TONE HORNS NOT WORKING  
BOTH HORNS ADJUSTED & TESTED

51509 CALL OUT LLANDUDNO AIR & AXLE LIGHT NOT WORKING  
EXAMINED NEW BULLA FITTED & TESTED.

51568 CALL OUT LLANDUDNO ALL ENDS CUTTING OUT  
51943 ALL RADDS FILLED & Sumps CHECKED & TOPPED  
UP, ENDS RUN UP & TESTED.

142028 CALL OUT LLANDUDNO BOTH GEARBOX FAULT NOTICES  
55619 PORISGET. FAULT RELAYS RESET & TESTED.

47306 BOTH COOLANT SYSTEMS LOW, SYSTEMS FILLED  
47365 & SEVERAL HOSE PIPE CLIPS SCREWED UP &  
TESTED

51938 CALL OUT LLANDUDNO HEATER NOT WORKING EXAM  
GLOW PLUG REMOVED CLEANED & REPLACED  
HEATER FIRED UP.

B.A. ROBERTS. P. COX.

SUNDAY: 24.12.89.

150119 AM COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED  
156461 & FILLED.

150119 GUARD REPORTED TOILET LOCKED OUT OF USE  
52119 TOILET PAN BROCKED & WONT FLUSH ALSO WASH  
BASIN TAP NOT WORKING. TOILET TANK FILLED  
PAN CLEANED & REPAIRS TO FLUSH VALVE &  
WASH BASIN WATER SYSTEM BRED OF AIL.

156461 GUARD REPORTED TOILET PAN BROCKED & WONT  
FLUSH TOILET PAN CLEANED & REPAIRS TO  
FLUSH VALVE ALSO N.H. SIDE TAIL WIND  
PULB RENEVED.

47405 CALL OUT STATION EARTH FAULT WONT BRIGHT  
EARTH FAULT DELAY RESET & TESTED

156281 CALL OUT STATION DA SIDE W/ WIPER NOT WORKING  
57281 EXAMINED REPAIRS TO CONTROL VALVE KNOB  
LOOSE ON SPINDLE.

156147 CALL OUT STATION DA REPORTED A.W.S  
ISOLATED ENROUTE. HORN WONT CANCEL  
OUT. A.W.S TESTED NO FAULT FOUND A.W.S  
RELEASED.

B. A. ROBERTS. P. COX.

NOV. 27-12-89.

156464 ALL COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED  
156455. & FILLED.

47125 CALLED TO WCCO WILL NOT START. EXAMINED COOLANT  
SYSTEM M.T. COOLANT SYSTEM FILLED - SEVERAL  
HOSE PIPE CLIPS SCREWED UP IN EQUIP ROOM  
WCCO RUN UP & TESTED

51947 CALL OUT LUNDUNO DR REPORTED ENG KEEPS  
CUTTING OUT. EXAMINED NO. 2 ENG SUMP OIL  
LOW. SUMP OIL FILLED ENG RUN UP & TESTED

53634 CALL OUT LUNDUNO DR HEATER NOT WORKING.  
WAXY GLOW PLUG REMOVED CLEANED & REPRICKED  
HEATER RUN UP & TESTED OK.

51426 CALL OUT LUNDUNO DR ALL ENGS CUTTING OUT  
53171 ALL PLATS FILLED ENGS RUN UP & TESTED.

156147 CALL OUT LUNDUNO DR REPORTED CAB HEATER BLOWING  
52147 CORD AIR. COOLANT SYSTEM BLED ON HEATER ELE-  
MENT. TESTED OK.

156421 CALL OUT LUNDUNO DR REPORTED ENG KEEPS  
52421 CUTTING OUT. EXAMINED COOLANT & SUMP OIL  
TOPPED UP & ENG RUN UP & TESTED

D. HILL M. PRICE.

150120 } CALL TO STATION DR REPORTED ENG SHUT-DOWN WILL.  
52120 } NOT RESTART FOUND COOLANT SYSTEM LOW WENT TO  
LUNDUNO COOLANT FILLED ENG RUN UP & TESTED

156406 CALL TO STATION GUARD REPORTED TOILET BLOCKED. WENT TO  
LUNDUNO. WATER TANK FILLED FLUSH TESTED. PAN CLEANED

53536 } CALL TO LUNDUNO DR REPORTED ENG'S CUTTING OUT ALL  
53494 } RADY FILLED SUMP OIL LOWERS CHECKED 53536 NO. 2  
ENG SUMP FILLED ENGINES RUN UP & TESTED

150201 } CALL TO LUNDUNO DR REPORTED UNABLE TO  
52201 } PLACE MASTER KEY SWITCH RESET. KEY FITTED & TESTED

53198 CALL TO STATION. DR REPORTED NO. 2 ENG WILL NOT  
START ENG STARTED. SUSPECT FUEL SYSTEM AIR LOCK CLEANED & TESTED

THURS. 28-12-89.

A. A. ROBERTS. M. PRICE 1200 - 2400

150119 AM COOLANT SYSTEMS & SUMP OIL LEVELS CHECKED  
156406 & FILLED.

53224 CALL OUT LLANDUDNO DR REPORTED ENGS  
51509 CUTTING OUT - ALL RADS FILLED ENGS RUN UP  
& TESTED.

150125 CALL OUT LLANDUDNO DR REPORTED EXHAUST  
52125 PIPE BLOWING ON ENG. EXAMINED SNAIGHT  
BLOW ON TURBO JOINERS UNABLE TO REPAIR  
A.D.C INFORMED

53494 CALL OUT LLANDUDNO DR REPORTED 2 ENG LIGHT  
BULBS MISSING. 2 NEW BULBS FITTED - TESTED

150143 CALL OUT LLANDUDNO GUARD REPORTED NO DOOR  
INTERLOCK LIGHT. EXAMINED DOOR REOPEN &  
CLOSED BOTH SIDES INTERLOCK LIGHT AGAIN.

D. HILL M. PRICE

51569 } CALL TO LLANDUDNO. DR REPORTED ENGS CUTTING  
53932 } OUT BUT ALL RADS FILLED SUMP OIL LEVELS CHECKED.  
ENGS RUN UP & TESTED.

150129. } CALL TO LLANDUDNO. DR UNABLE TO COUPLE  
52129. } SET. FOUND COUPLER PISTON STUCK BUT RELEASED  
SET COUPLED & TESTED. BRAKES RELEASED & POWER  
REBAINED. SET WORKED FORWARD.

51418. CALL TO STATION. DR REPORTED BUZZER IN CAB.  
NOT WORKING SWITCH ADJUSTED & TESTED.

53931 } CALL TO STATION GUARD REPORTED LIGHTS WILL NOT  
54280 } WORK FROM THROUGH CONTROL SWITCH IN VAN.  
FOUND NO 6 FUSE BLOWN. TEMP REPAIR CARRIED  
OUT LIGHTS TESTED REPAIRS CARRIED OUT @  
LLANDUDNO.

156407 } CALL TO LLANDUDNO. GUARD REPORTED R. W.  
57407 } SIDE INTERLOCK LIGHT NOT WORKING FOUND  
BULB BLOWN NOW BULB FITTED & TESTED



